



HP Virtual TapeServer for NonStop – server and software updates

HP is pleased to announce that, effective September 14, 2009; HP Virtual TapeServer (HP VTS) will release several new product offerings to the HP VTS product line. The new HP VTS product changes are described below:

HP VTS Server Updates:

VT5900-K: new HP VTS Base server, using the ProLiant DL185G5, will be made available under Controlled Availability (CA) on September 14, 2009.

VT5900-6TB: new Add-on HDD for the VT5900-K server that provides 6x1TB SATA drives, yielding 6TB raw storage, will be available under Controlled Availability (CA) on September 14, 2009.

VT5900-FC4: new Add-on 4Gbps dual port Fibre Channel HBA for the VT5900-K server for external physical tape connectivity will be available under Controlled Availability (CA) on September 14, 2009.

HP VTS Software Product Updates:

VT5900-K00: new HP VT5900-K VTS Software License for VT5900-K, includes 2x Virtual Tape Drive (VTD) licenses, with combined compression capability, will be available under Controlled Availability (CA) on September 14, 2009.

All other HP VTS software licenses and available product features remain the same. HP VTS servers are compatible with all versions of S-Series, NS-Series and NonStop BladeSystem servers.

Prices, detailed descriptions, and additional requirements for these products will be available in QMS on September 14, 2009.

Affected products and schedule details

Affected components: September, 2009

Part no.	Product name
VT5900-K	HP Virtual TapeServer Base version (Proliant DL185G5) **NEW**
VT5900-6TB	HP Virtual TapeServer 6TB internal storage **NEW**
VT5900-FC4	HP Virtual TapeServer 4Gbps dual port Fibre Channel HBA **NEW**
VT5900-K00	HP Virtual TapeServer Software License for VT5900-K **NEW**

© Copyright 2009 Hewlett-Packard Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

For more information, go to www.hp.com/go/nonstop

